


**AUTO-HAK Sp. z o.o.**

ul. Słoneczna 16K 76-200 SŁUPSK  
POLAND

tel/fax +48 59 8 414 414; +48 59 8 414 413

e-mail: [office@autohak.com.pl](mailto:office@autohak.com.pl)

[www.autohak.com.pl](http://www.autohak.com.pl)



**AUTO-HAK**

**DACIA LOGAN  
MCV II KOMBI**

Nr kat.

**G81**



07.2013 → 12.2016

01.2017 →



E20-55R-01 3506

**D**

7,59 kN




R=1300 kg



S=75 kg



1h



FULL VERSION INSTRUCTION




śruba	Nm	M6	M8	M10	M12	M14	M16
klasa 8.8		9,9	24	48	83	132	200
klasa 10.9		14	34	67	117	185	285












0 km →



1000 km



1		1		8	M12x75	1
				9	M12x70	1
				10	M12x40	6
				11	M10x90	4
				12	∅ 13	8
2		1		13	∅ 30x∅10.5x2.5	8
				10	DIN 9021	
3		1		14	∅ 12.2	8
				15	∅ 10.2	4
4		1		16	M12	8
				17	M10	4
5		1	18			1
6		4				
					∅20x4, L=61mm	
7		4				
					∅35x∅21x10mm	



- 2x M10x90mm
- 2x  $\varnothing 30 \times 10,5 \times 2,5\text{mm}$

05

